

PE-TH8010 Temperature Humidity Meter With Dew point**Key Features:**

A 4-parameter measuring instrument designed to provide accurate humidity, dew point and temperature reading results. Equipped with dual display, displaying 2 reading results at the same time. It also have special functions such as data hold, MAX and MIN values, backlight and auto power off and operates on three AAA batteries only.

PE-TH8010 Temperature Humidity Metert With Dew Point

The **PE-TH8010** is a humidity and temperature measuring instrument. It is normally used to measure the humidity and temperature in offices, storerooms, buildings and greenhouses.



SPECIFICATIONS:

- Measure Parameters: °C, °F, %RH(relative humidity), td(dew point temperature)
- Range: -10 ~ +50°C, +14 ~ +122°F, 0 ~ +100%RH
- Resolution : 0.1°C, 0.1°F ; 0.1%RH
- Accuracy: ±1.0°C, ±1.8°F, ±3%RH (5~95%RH)
- Sample Rate:1 time sec
- Display: 4 digits LCD Display
- Auto power off : About 20min
- Dimension:121 x 60 x 30mm
- Weight : 180g
- Power Supply: DC1.5V (AAA) x 3pcs

Accessories include:

- Free 1.5V x3AAA batteries
- Free protect cover
- Free protective carrying case
- Free Wrist Strap/String
- User's Manual